




## Technical Bulletin – May 15, 2015

### 360 Y-DROP™ John Deere 4730/4830

On some models of the John Deere 4730 and 4830 model sprayers, 360 Yield Center dealers and farmers have encountered situations in which the first boom section has difficulty extending out of its cradle after 360 Y-DROP system is installed. This is an issue that some sprayers of this model have encountered without 360 Y-DROP installed. As a result, John Deere has provided a service part for shimming the boom enough to unfold. The John Deere service part number is **N314067**.

If you are experiencing these extension difficulties on your John Deere 4730 or 4830 sprayer, please order the service part from <https://jdparts.deere.com> and see photos below on shim placement to alleviate the issue.





Shims added to both boom mount locations to lift the end of the booms out of their cradles.