



## Technical Bulletin – June 11, 2015

### **360 Y-DROP™ Variable Rate Nozzles**

It has come to our attention that the charts for variable rate nozzles in the 360 Y-DROP Technical Guide, provided by Greenleaf, have some errors that are giving incorrect application rates based on pressure. A new accurate chart is in the 360 Y-DROP [Technical Guide](#) – please see pages 18-19.

In many cases, there will be no issue reaching the desired application rate. Issues may occur in 22 in. and 20 in. rows, and in 30 in. rows where 02 nozzles are being used with application rates below 15 GPA. In these cases, the 02 nozzles should be replaced with 015 nozzles.

For example:

- 015 nozzles will get 10-24 GPA at 8-9 mph
- 02 will get 15-34 GPA at 8-9 mph

If you would like to replace and return your old nozzles, please call the Support Center at 888-512-4890. If you would like to purchase 015 nozzles in addition to what you already have, please order these from the [Dealer Store](#) and we will expedite the shipping to you.